

## Product Change Notification

M-105.20, M-105.2B, M-105.30, M-105.3BA, M-105.3BB, M-105.81 and M-106.10, M-106.20, M-106.30

### Change Description

The above mentioned products of the M-105 series and the complete M-106 series will be discontinued.

### Impact and Reasons

The affected products have reached their end of life and are thus being phased out.

### Recommended Action

Customers looking for a replacement should consider the remaining products within the M-105 series such as M-105.10, M-105.11, M-105.1B, M-105.1P, M-105.2P and M-105.3P.

### Schedule

Last Time Buy	Last Delivery
2019-06-14	2019-06-28

### Affected Products

Product number	Change	Effective date	Successor	Alternative products
M-105.20	Discontinued	2019-06-14	-	2x M-105.10
M-105.2B	Discontinued	2019-06-14	-	2x M-105.1B
M-105.30	Discontinued	2019-06-14	-	3x M-105.10 and 1x M-009.10
M-105.3BA	Discontinued	2019-06-14	-	3x M-105.1B and 1x M-105.VB1
M-105.3BB	Discontinued	2019-06-14	-	3x M-105.1B and 1x M-009.10
M-105.81	Discontinued	2019-06-14	-	3. M-105.11 and 1x M-105.VB1
M-106.10	Discontinued	2019-06-14	-	-
M-106.20	Discontinued	2019-06-14	-	-
M-106.30	Discontinued	2019-06-14	-	-